DART SERVICE BULLETIN SB10-5

AFFECTING:

D412-694-011 SPACEDOOR™INSTALLATION, B/N B36652 D3117-1 SEAL, B/N B33187 D3117-3 SEAL, B/N B33188

> REF FAA STC: SR02086NY REF TCCA STC: SH05-10 REF EASA STC EASA.IM.R.S.01085


Purpose:

D3117-1 Seal b/n B33187 and D3117-3 Seal b/n B33188 does not meet required dimensions and may allow the window to unintentionally pop-out. This seal was used during assembly of D412-694-011 Spacedoor Installation b/n B36652.

Instructions:

For customers who have received replacement seal or spacedoor installation with the affected batch number, contact DART to have the seal replaced.

If batch number is unknown, the following diagram can be used to identify non-conforming seal.



Α	A NEW ISSUE			CP	10.07.07
REV.			DESCRIPTION	BY	DATE
DESIGN		P	DART AEROSPACE LTD		
. DRAWN			HAWKESBURY; ONTARIO, CANADA		
CHECKED		_8	DRAWING NO.		REV. A
MFG. APPR.		N/A	SB10-5 SHEET 1 OF		SHEET 1 OF 1
APPROVED		111	TITLE	-	SCALE
DE APPR.		-4	SERVICE BULLETIN		NTS
DATE 10.07.07			COPYRIGHT © 2010 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT		